

0
10
20
30
40
50
60
70



Service • Assistenza • Dienstverlening • Serwis •
Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam •
Nazwa • Jméno • Názov • Név •
Denumire • Ísim • Название

SALVADOR



Nr. • No. • N° •
Номер • Č • Sz

SAD52T12


Typ • Type • Tip •
Typus • Tipo • Тип

12

31




PR4




X...

M25




4x25 mm X...

C3




X...

W1




X...

L4



X...

J11



X...

P13




3,5x13 mm X...

G22




φ18 X...

T17




φ 8 X...

ZM1




X...

S4



3x16 mm X...

F58




X...

S20




4x20 mm X...

B1




φ 8x28 mm X...

M1



X...

T1




X...

W3




X...

T6




X...

MH2




H=2 X...

T32




X...

S17




3,5x17 mm X...

MW1



X...

MW2



X...

G5




X...

G4




X...

P16




3,5x16 mm X...

J23




X...

P35



4x35 mm X...

PZ1



X...

