











EASY TYP 103



EASY TYP 103

MM

260

250

240

230

220

210

200

190

180

170

160

150

140

130

120

110

100

90

80

70

60

50







40


30

20




10

0


A0 8 x 30mm 	B1 f 7 x 50 mm 	C0 
C2 	C7 16mm 	D0 3 x 15 mm 
D5 3,5 x 16 mm 	D16 4,2 x 28 mm 	D21 5 x 13 mm 
E0 5 x 50 mm 8 x 50 mm 	K 4mm 	L5 
M1 	N1 L-300 	P0 
P20 	T3 	




EASY TYP 103









1	812	350	16	x1	1/2
2	812	350	16	x1	1/2
3	629	157	16	x4	1/2
4	682	187	16	x4	1/2
5	639	294	2,8	x4	1/2
6	760	696	2,8	x1	1/2
7	686	52	16	x1	2/2
8	300	160	16	x4	2/2
9	300	160	16	x4	2/2
10	686	100	16	x1	2/2
11	686	332	16	x1	2/2
12	284	120	16	x4	2/2
13	720	360	22	x1	2/2
					1/2






1 ▶

A0 8 x 30mm 	C2 	C7 16mm 
D0 3 x 15 mm 	D21 5 x 13 mm 	N1 L-300 
T3 		




2

A0 8 x 30mm 	C2 	C7 16mm 
D0 3 x 15 mm 	D21 5 x 13 mm 	N1 L-300 
T3 		




3

C2 	D21 5 x 13 mm 	P0 
--	--	--




4 ▶

A0 8 x 30mm 	C7  16mm
x4	x4










5 ▶

A0 8 x 30mm 	C7  16mm
x2	x2






6 ▶




A0 8 x 30mm 	D5 3,5 x 16 mm 	P20 
T3 		
x2	x4	x4




7 ▶





8 ▶










9 ►












10 ►




11▶



12




13 ►




A0	8 x 30mm	x8
		
C7		x8
16mm		


14 ►




A0	8 x 30mm	x8
		
C7		x8
16mm		


15 ►




A0	8 x 30mm	x16
		

16 ►





A0	8 x 30mm	x16
		
C7		x4
16mm		


17▶






18▶



19 ►





20 ►






21▶

D0 3 x 15 mm 	x24	D5 3,5 x 16 mm 	x24	M1 	x24
				N1 L-300 	x4



a=b



22▶

