























EASY - TYP 307




Ø8



EASY - TYP 307

A0 8 x 30mm 	B0 	B1 f 7 x 50 mm 
C0 	C2 	C7 16mm 
C10 6.3 x 20 mm 	C13 6.3 x 16 mm 	D0 3 x 15 mm 
D5 3.5 x 16 mm 	D10 4 x 16 mm 	D16 4,2 x 28 mm 
D21 5 x 13 mm 	E0 5 x 50 mm 8 x 50 mm 	J4 
J5 	J6 	K 4mm 
L5 	M1 	N3 L-450 
O1 	P0 	P20 
Q3 	Q4 	
S0 L-1012 	T3 	
U0 		


EASY - TYP 307




1	1912	528	16 x1	1/5
2	1912	528	16 x1	1/5
3	1850	510	16 x1	3/5
4	1541	52	16 x1	5/5
5	1541	510	16 x1	3/5
6	506	488	16 x3	4/5
7	1019	488	16 x1	3/5


8	367	490	16 x1	4/5
9	514	490	16 x1	3/5
10	440	157	16 x2	5/5
11	450	160	16 x2	5/5
12	450	160	16 x2	5/5
13	511	187	16 x2	4/5
14	1854	511	16 x2	2/5

15	1476	511	16 x1	4/5
16	1575	538	22 x1	5/5
17	1541	46	22 x1	5/5
18	1860	1028	2.8 x1	1/5
19	1860	516	2.8 x1	1/5
20	443	450	2.8 x2	1/5
S0			x1	5/5
				5/5





1 ►

C2  x6	D21 5 x 13 mm  x2	P0  x2
Q4  x2		






2 ►

T3  x4







3▶

A0	8 x 30mm	x4	C7	16mm	x4
-----------	----------	-----------	-----------	------	-----------






4▶



A0	8 x 30mm	x2	D5	3.5 x 16 mm	x6	P20		x6
T3		x4						






5▶

A0 8 x 30mm x4 	C2 x4 	C7 x4 16mm 
---	--	--




C10 6.3 x 20 mm x2 	J6 x8 
Q3 x6 	T3 x4 








6 ▶

A0	8 x 30mm	x4
C7	16mm	x2
Q3		x6







7▶

(C2)		x2
(C13)	6,3 x 16 mm 	x2
(D0)	3 x 15 mm 	x2
(D21)	5 x 13 mm 	x8
(J6)		x3
(N3)	L-450 	x2




8▶

(A0) 8 x 30mm  x4	(C7) 16mm  x2	(D0) 3 x 15 mm  x2
(D21) 5 x 13 mm  x8	(N3) L-450  x2	




9▶


(A0) 8 x 30mm  x2	(C2)  x2	(C7) 16mm  x2
--	--	--





10▶





11▶






12▶





13▶




14▶





15▶







16▶



17▶







18▶






19▶▶

D0 3 x 15 mm 	x32	M1 	x32
---	------------	--	------------











20▶

(D5) 3.5 x 16 mm x4 	(S0) L-1012 x1  0
--	---




21▶




22▶

D10 4 x 16 mm 	x16	J4 	x8
--	------------	--	-----------






23▶

D10 4 x 16 mm 	x6	J5 	x3
--	-----------	--	-----------





24▶



D16 4,2 x 28 mm 	x6	L5 	x3	U0 	x4
--	-----------	--	-----------	--	-----------





25▶





26▶




27▶





28▶



29▶




30▶







31▶




D0 3 x 15 mm  x16	D5 3.5 x 16 mm  x12	M1  x16
N3 L-450  x2		



a=b



32▶



33 ▶

