



ASSEMBLY INSTRUCTIONS -17020010/01


PART LIST

1		x2
2		x1
3		x12
4		x2



HARDWARE LIST

NO.	DESCRIPTION	Q.TY
A	M6x25 	24
B	Ø6x16x1 	24
C	M4x60 	2
D		6


STEP 1





STEP 2





STEP 3



STEP 4




ASSEMBLY INSTRUCTIONS - 17020010/01



ASSEMBLY INSTRUCTIONS - 17020010/01


PART LIST

1		x1
2		x4

HARDWARE LIST

NO.	DESCRIPTION	Q.TY
A	M6x50 	8
B	Ø6x13 	8
C	Ø6x16x1 	8
D	M4x60 	1

STEP 1



STEP 2

