









XL 129



COLLI 1/2				
E	2004	x	100	1
C	2000	x	280	2

COLLI 2/2				
A	1050	x	480	1
B	1050	x	180	1
H	384	x	80	3
G	1046	x	257	1
A1+B1	400	x	170	2
C1	1014	x	170	1
D1	1024	x	394	1
F	317	x	100	4



0013K	1x	0001K	24x	0018K	16x
		 8x40			
0054K	4x	0055K	4x	0019K	16x
0038K	32x	0002K	8x	0003V	16x
		 3x16			
0006V	12x	0004K	4x	0011U	2x
 4x16					
0065K	6x	0041K	4x		
0005V		12x			
 7x50					



1)





0002K	8x	0003V	16x
 3x16			





2)

0001K	24x
 8x40	

6)

0038K	16x	0018K	12x
			





11)

$$X=Y$$



0004K

4x

