




SPARKS 30J6_51

























NO	Dim.[mm]			Col.-No	Qty
1	1350	600	20	1/1	1
2	1318	150	22	1/1	1




20 min







SPARKS 30J6__51


D20	
x6	ESØ6,3x9,5

KR3	
x3	Ø10




B11	
x5	Ø7x50

G4	
x5	







G2	
x1	



1



2



3

