







Assembly Instruction

KOMMODE MALIN


Article number: 05540001/02+32




565 X 1 PCS 	180964 X 1 PCS 	286 X 1 PCS 	95200 X 1 PCS 	145662 X 16 PCS 		
249 X 5 PCS 	147 X 20 PCS 	175 X 16 PCS 	361 X 8 PCS 	150217 X 4 SET 	150218 X 4 SET 	157124 X 12 PCS 
100 X 24 PCS 	101 X 24 PCS 	172 X 8 PCS 	4997 X 16 PCS 	298177 X 4 PCS 	298188 X 4 PCS 	22018 X 26 PCS 

Diagram illustrating the assembly of the second part of the frame. The main view shows a rectangular frame with four corner brackets (298188) and four side brackets (249) being attached. A circular inset shows a close-up of a corner bracket (298188) being secured with a screw (100). Another circular inset shows a side bracket (249) being secured with a screw (100). A third circular inset shows a side bracket (249) being secured with a screw (100). A fourth circular inset shows a side bracket (249) being secured with a screw (100). A red text box indicates: "TURN AROUND THE PIECE (PART) !".


3




4




5




6




7




8




9



10



11



12

