







BAS 100/115 Z




max.
5kg

KUH.30005
KUH.40011
KUH.40013













 A 18	 B 12	 C 2	 D2 2	 E 2	 E1 12	 HG 4
 J 4	 L2 7	 O 1	 P5 8	 P11 20-25	 R2 4	 S30 2



ISM-KUH-00914


1

±8x30mm	±35/0mm	±3.5x13mm
		
A	HG	P5
14	4	8




2

6,4 x 50mm



B

6







O

1




E1

6




3

6,4 x 50mm



B

6






O

1






E1


6






4



5

	ø3.0x16mm
L2	P11
7	20-25





6

+5/19mm






J

4



7



8

4.0x30mm






R2

4







S30

2




KUH.70021




9

±15/12mm



C

2



10

±8x30mm

L=20mm



A

4



D2

2

