









Tia-New

05860025 / 03



festziehen / tighten / Затягивать /
serrer / stringere / utáhnout / vasttrekken /
zategnuti / strângere / zwiázac / zacisn'æ
szorosan meghúzni / pevne dotiahnuť /
trdno pritegniti / затянуть / dra et



eindrücken / press in / enfoncer / wcisnąć
ribattere / zatlačit / Вкарайте / indrukken
benyomni / stlačit' / vtisniti / tryck in
introducere prin apăsare / вдавить



ausmessen / measure / mesurer /
misurare / opmeten / izmeriti / mīara /
kimérni / izmeriti / măsurare / измерить
změřit / Измерете / māt upp / zmierzyc



drücken / press / presser / stisknout /
Натиснете / vtisniti / nasinac / drukken /
pritisnuti / nacinac / pritisniti / нажать /
(meg)nyomni / apăsare / tryck fast / nacinac




einschlagen / hammer in / beverni / sla in
frapper au marteau / infossare / Zabit' /
zarazit / Набийте / zabiti / wbić
introducere prin bătaie / забить / zatlouct







Drehen - wenden / przekreć / odwrócić /
Keren - omdraaien / Girare - Ruotare /
Okrenuti - ubrnuti / Retourner - renverser /
Turn over - turn around / Otočte - obratite /
Завъртете - обърнете / Obrnite list /
Întoarceți - roțiți / Vrid runt - vänd /
прокрутить / повернуть / otočit - obrátit
elforgatni - megfordítani





L H B
500x375x420mm












				
1	a1	354mm x 400mm x 16mm	1	8/15
2	a2	354mm x 400mm x 16mm	1	8/15
3	b1	504mm x 420mm x 16mm	1	8/15
4	c1	468mm x 380mm x 16mm	1	8/15
5	d1	496mm x 168mm x 18mm	1	8/15
6	e1	350mm x 80mm x 16mm	2	8/15
7	f1	350mm x 80mm x 16mm	2	8/15
8	g1	410mm x 80mm x 16mm	2	8/15
9	h1	355mm x 440mm x 3mm	2	8/15
10	i1	484mm x 360mm x 3mm	1	8/15













1  Ø15x12mm x12	2  Ø6x45/34mm x12	3  3.5x16mm x31	4  8x35mm x12	11  M4x20mm x4
5  Ø7x50mm x4	24\RL  350 mm x2	24\DL  350 mm x2	24\CR  350 mm x2	24\CL  350 mm x2
86  192mm x2	46  Ø15mm x4	25  6x16x53mm x4	 4mm x1	















4	 8x35mm	x4	2	 Ø6x45/34mm	x4
1	 Ø15x12mm	x4	3	 3.5x16mm	x12
24\CL			24\CR		
 350 mm			 350 mm		
x2			x2		























x2




 A=B!







25  6x16x53mm x4

69  9x20x100mm x4

3  3.5x16mm x15

