








ASSEMBLY INSTRUCTIONS:12540056/01

No	Name of Hardware	Fig	Q.ty		
1	Screw 6x60		4	 A	 B
2	Allen Key		1		




ASSEMBLY INSTRUCTIONS:12540056/01

Step 1:




2x

Step 2:



2x

Step 3:



2x