
















H1		x4 ø 8x30	H4		x8 ø 10x40	A20		x4 ø 4x16
D196		x4 ø 15x14	D197		x4 M10x7,5	D198		x4 ø 7x34 M6
A172		x1 6 mm	D119		x8	D217		x8 B55/M6
D10		x8	A5		x1 4 mm	A22		x2 ø 7x70
E102		x4 ø 20						





D198	 x4 ø 7x34 M6	D217	 x8 B55/M6	E102	 x4 ø 20
------	---	------	--	------	--








H1		x4 ø 8x30	D196		x4 ø 15x14	D119		x8
H4		x8 ø 10x40						

2




D197		x6 M10x7,5	A5		x1 4 mm	A172		x1 6 mm
------	---	---------------	----	---	------------	------	---	------------


3




D10		x2	A20		x4 ø 4x16
-----	---	----	-----	---	--------------

4



A22		x2 ø 7x70	A5		x1 4 mm
-----	---	--------------	----	---	------------

5



D10



x6

6

