








PIVOT





30min






PZ2



I



II



Bx5



H= 150 mm

Cx1




H= 150 mm

Dx1



H= 130-200 mm

Ex5



8x25

Fx20




5x30



PZ2

Gx1



H=5 mm


1

Bx2



H= 150 mm

Ex2



8x25




Fx8



5x30



PZ2



2

Bx3




H= 150 mm

Cx1




H= 150 mm

Dx1



H= 130-200 mm

Ex3



8x25

Fx12




5x30








PZZ






Gx1



H=5 mm



3



4

