






JASPER




30min



PZ2 PH3




Ax1




H=195 mm


Bx2



H=195 mm




Ax2





H=195 mm

Bx1





H=195 mm


I



II




Cx1



H=170-200 mm

Dx1



H=195 mm

Ex2



H=195 mm

Fx4




5x30



PZ2

Gx7



6x25



PH3

Hx13




6x40










PH3

1




V




2

Ax1




H=195 mm

Bx1




H=195 mm

Cx1



H=170-200 mm

Dx1




H=195 mm

Ex1



H=195 mm

Fx4



5x30



PZ2






Hx13




6x40



PH3



3



4

