
















KIMI




2/8

KIMI



nr	L[mm]	B[mm]	T[mm]	Menge	Coll.
1	1210	498	28	1	1/2
2	450	478	16	1	1/2
3	720	492	28	1	1/2
4	584	478	16	1	2/2
5	584	478	16	1	2/2
6	727	120	16	1	2/2
7	616	429	3	1	2/2
8	350	120	16	1	2/2
9	414	120	16	1	2/2
10	444	203	16	3	2/2
11	400	100	12	1	2/2
12	400	100	12	1	2/2
13	384	100	12	1	2/2
14	616	429	3	3	1/2




A3 ø6x42 x...(12)	A1 ø7x50 x...(4)	W2 x...(1)	F4 x...(2)	F12 x...(6)
H5 400mm x...(6)	I1 x...(6)	W1 x...(2)	G46 6x8 x...(12)	
K1 ø15x12 x...(10)	G8 4x30 x...(6)	N1 M4x9 x...(6)	W3 x...(6)	G34 3,5x16 x...(28)
K5 x...(10)	B1 ø8x35 x...(10)	I7 x...(10)	P4 x...(8)	E1 128mm x...(3)

3/8


KIMI




I












x3



0,5h



II




4/8




KIMI



III



IV






5/8


KIMI





V



VI



VII





6/8




KIMI



VIII



IX






7/8



KIMI



X

 $a=b$ 

XI



8/8

KIMI



XII

