




















 A.8 x14 $\varnothing 4 \times 20$	 A.21 x24 $\varnothing 4.2 \times 19$	 A.27 x16 $\varnothing 6,3 \times 13$
 B.9 x4 $\varnothing 8 \times 30$	 B.12 x18 $\varnothing 12 \times 30$	 B.15 x10 $\varnothing 7 \times 50$
 B.17 x8 $\varnothing 7 \times 70$	 B.50 x1 $\varnothing 4$	 F.28 x4
 F.26 x2	 F.27 x2	
 E.35 x8 $M6 \times 30$	 G.2 x1 35×35	







2



5







3





6

4




7


5




8



6




4x



9

7



10

