


















Modell **TYP C**






A	B (mm)		C
1	402	330	1/1
2	402	330	1/1
3	800	350	1/1
4	800	350	1/1
5	402	310	1/1
6	374	300	1/1
7	780	416	1/1
8	396	396	1/1
9	396	396	1/1




1x 4mm z1	6x Ø 6,3x50mm e27	8x Ø 5mm d1
6x Ø 15x12mm r1	6x 45mm r23	1x L=75x25x15mm n14/2
4x Ø 35mm a1	4x 40x50x12mm b1	6x Ø 20mm s1
8x 10x10x15mm l2	5x 25x45x45mm k43	1x Ø 8x50mm y1
2x Ø 4,2x16mm p21	5x Ø 4x25mm p23	4x Ø 4x25mm p26
2x Ø 3x16mm p50	8x Ø 3,5x16mm p51	1x Ø 5x50mm p60
2x L=96/128mm c238	12x Ø 8x30mm f1	



1

f1 x 12



Ø 8x30mm

r1 x 6



Ø 15x12mm

d1 x 8












Ø 5mm

b1 x 4




40x50x12mm




2

r23 x 6



45mm

n14/2 x 1







L=75x25x15mm

p50 x 2



Ø 3x16mm






3

s1 x 6



Ø 20mm



4

e27 x 6



Ø 6,3x50mm

z1 x 1



4mm

l2 x 8




10x10x15mm

k43 x 5



25x45x45mm

p23 x 5






Ø 4x25mm




p21 x 2




Ø 4,2x16mm



$XX=YY=90^\circ$



5



6

p26 x 4




Ø 4x25mm

p51 x 8




Ø 3,5x16mm

a1 x 4







Ø 35mm

c238 x 2



L=96/128mm



7

p60 x 1



Ø 5x50mm

y1 x 1



Ø 8x50mm

