












27980269/01
BJÖREN

BDSK Handels GmbH & Co. KG
Mergentheimer Straße 59
DE-97084 Würzburg
E-Mail: info@xxxlutz.at









A	x24	B	x28	C	x12	D	x32	E	x13	F	x1	G	x12
													
6x35mm		Ø15x12mm		8x30mm		3.5x14mm		7x39mm		M4		4x35mm	
H	x6	I	x6	J	x8	K	x6	L	x26	M	x4	N	x2
													
340mm		340mm		4x20mm		8x20mm		Ø20mm		Ø48x30mm		M8x70mm	
O	x2	P	x2	Q	x2	R	x2	S	x2	T	x1	U	x6
													
100x20x3mm						M8		M8					
V	x10	W	x2	X	x2	Y	x4	Z	x2	a	x2	b	x2
													
M6x20mm				40x30x5mm		M4		6x30mm		4x35mm			




Assembly details




1




A	x2	C	x2
			
6x35mm		8x30mm	

2




D	x12	H	x6
			
3.5x14mm		340mm	


3




B	x2
	
Ø15x12mm	

4




C	x4
	
8x30mm	


5



6





7



C	x4
	
8x30mm	

8



Y	x2	D	x2	b	x2	A	x4
							
M4		3.5x14mm				6x35mm	


The diagram illustrates a mechanical linkage system. A main frame (labeled 4) supports two vertical links, each pivoted at the bottom (labeled O) and connected to a horizontal link (labeled E) at the top. A detailed view of the pivot joint shows a vertical link (labeled E) passing through a horizontal link (labeled F) which is pivoted on a vertical support (labeled E). Another detailed view shows a vertical link (labeled N) passing through a horizontal link (labeled N) which is pivoted on a vertical support (labeled N). A table at the bottom right lists the components and their counts:

F	x1	E	x4	N

F	x1	E	x4	N	x1	O	x2
							
M4		7x39mm		M8x70mm		100x20x3mm	


B	x2	P	x2	N	x1
					
Ø15x12mm				M8x70mm	

11




Q	x1	R	x1	S	x1	T	x1
							
		M8		M8			

12




13




B	x2
	
Ø15x12mm	

14




Q	x1	R	x1	S	x1	T	x1
							
		M8		M8			


15




F	x1	B	x4	V	x4
					
M4		Ø15x12mm		M6x20mm	


16




W	x2	L	x8	C	x2
					
		Ø20mm		8x30mm	

17




A	x6
	
6x35mm	

18




E	x3	F	x1
			
7x39mm		M4	

19




X	x2
40x30x5mm	

20




B	x6
Ø15x12mm	

21




D	x6	U	x6
			
3.5x14mm			

22




Y	x2	Z	x2	a	x2
					
M4		6x30mm		4x35mm	


23





x3

G	x12
	
4x35mm	


24




A	x12
	
6x35mm	





B	x12	L	x12
			
Ø15x12mm		Ø20mm	





L	x6	F	x1	K	x6	V	x6
Ø20mm		M4		8x20mm		M6x20mm	

28



29

