


















GHIA



ART 07780059-01

xora



1,5h






nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	1380	600	28	1	3/3
2	1316	388	16	1	3/3
3	729	500	28	1	1/3
4	536	496	16	1	1/3
5	536	496	16	1	1/3
6	536	476	16	1	1/3
7	500	450	16	1	1/3
8	970	64	16	2	2/3
9	384	64	16	2	2/3
10	527	184	16	3	2/3
11	400	140	12	3	3/3
12	400	140	12	3	3/3
13	400	140	12	3	3/3
14	460	401	3	3	1/3
15	1050	496	16	1	2/3
16	1050	496	16	1	2/3
17	1316	81	28	1	3/3
18	97	444	28	1	3/3
19	548	514	3	2	1/3



	G14 3,5x45 x...(2)	I11 ø8 x...(4)	F16 ø4 x...(4)	N7 M4x15 x...(1)
I18 x...(1)	A1 ø7x50 x...(6)	W2 x...(1)	F4 x...(4)	F15 x...(10)
A6 ø7x40 x...(12)	I1 x...(12)	H24 H35-400mm x...(3)	W1 x...(2)	G20 5x13 x...(24)
K1 ø15x12 x...(14)	G8 4x22 x...(6)	S2 x...(5)	P4 x...(10)	G34 3,5x16 x...(53)
K10 x...(14)	B1 ø8x35 x...(24)	I7 x...(10)	E100 192mm x...(3)	

I

K10



x...(10)

F15



x...(10)



G34




3,5x16

x...(10)



F15




K10



15





K10




1

II




H24



H35-400mm x...(3)

H24

III




0,5h

W1



x...(2)




A6



Ø7x40


x...(12)

W2



x...(1)

III



A6



Ø7x40



X

A1




Ø7x50



✓

A6



I1



x...(6)



G20



5x13

x...(12)


H24




H35-400mm x...(3)

 $a=b$



III





H24



G20



IV



P4



x...(2)

K1



ø15x12 x...(14)


B1




ø8x35

x...(24)


K10



x...(4)



IV



K1




ø15x12 x...(4)


B1



ø8x35 x...(8)



IV



K1




ø15x12 x...(6)

B1




ø8x35 x...(12)




V


G34 
3,5x16 x...(30)



1.






2.



VI



F4 
x...(4)

G34 
3,5x16 x...(8)




VII

P4






VIII


A1





W2



IX



X



XI

G34

I1

I1



x...(6)

S2





x...(5)

G34




3,5x16


x...(5)

 $a=b$ 



R





L



XII






 $\varnothing 5$ 

R

 $\varnothing 5$ 


L

XIII








XIV






G14



3,5x45 x...(2)



XV






XVI



N7



M4x15

x...(1)







XVII

G20
5x13 x...(12)




F16
Ø4 x...(4)

H24
H35-400mm x...(3)



XVIII

G8 4x22	 x...(6)	E100 192mm x...(3)
------------	--	--------------------------






XIX

- I11

Ø8

x...(4)
- I7

x...(10)



XX

