










LIZA



05860001 / 03
05860001 / 04
05860001 / 05



L H B
400x805x480mm



1	a1	775mm x 480mm x 16mm	1	3/7
2	a2	775mm x 480mm x 16mm	1	3/7
3	b1	396mm x 170mm x 16mm	4	3/7
4	c1	368mm x 80mm x 16mm	2	3/7
5	d1	368mm x 80mm x 16mm	2	3/7
6	e1	400mm x 600mm x 30mm	1	3/7
7	f1	350mm x 80mm x 16mm	4	3/7
8	f2	350mm x 80mm x 16mm	4	3/7
9	g1	355mm x 340mm x 3.2mm	4	3/7
10	h1	306mm x 80mm x 16mm	4	3/7
11	i1	715mm x 382mm x 3.2mm	1	3/7



festziehen / tighten / Затягивать /
serrer / stringere / utáhnout / vasttrekken /
zategnuti / strângere / zwiászc / zacisnąć /
szorosan meghúzni / pevne dotiahnuť /
trdno pritegniti / satvaytu / dra et




einrücken / press in / enfoncer / wcisnąć /
ribattere / zatlačit / Вкларяте / indrukken /
benyomni / stlačit / vtisni / tryck in /
introducere prin apăsare / apasaytu



ausmessen / measure / măsurar /
misure / opmeten / izmerti / miera /
kimérni / izmerti / măsurare / измерить /
zmért / mäsere / mät upp / zmierzyc

drücken / press / presser / stisknout /
Hármocherà vtisni / nasinac / drücken /
pritisnuti / nacinac / pritisni / hasarny /
(meg)nyomni / apasare / tryck fast / nacinac

einschlagen / hammer in / bevern / sla in /
frapper au marteau / infosare / Zabit /
zarazit / Hačúäte / zabiti / wbić /
introducere prin bătăie / ačúäte / zatloucť

Drehen - wenden / przekreć - odwrócić /
Keren - ondraaien / Girare - Ruotare /
Okrenuti - ubrnuti / Retourner - renverser /
Turn over - turn around / Otočte - obráte /
Zaopreite - obăşere / Obrnite list /
Intoarceți - roțiți / Vrid runt - vänd /
повернуть - поберыть / otocit - obrátit /
elforgått - megfordítani






1  Ø15x12mm x8	5  Ø7x50mm x16	3  Ø3.5x16mm x54	4  Ø8x35mm x16	47  Ø8mm x4
33  4.0x35 x4	69  9x20x100mm x4	72  x4	45  Ø8x1mm x8	46  Ø15mm x4
2  Ø6x45/34mm x8	24\RL  350 mm x4	24\DL  350 mm x4	24\CR  350 mm x4	24\CL  350 mm x4



3  x10
 Ø3.5x16mm x10



69  x4

A=B





I

II





III

IV



V



1 Ø 15x12mm x2	2 6x45/34mm x2	4 Ø 8x35mm x2	5 Ø 7x50mm x2
24\DL 350 mm x1	24\RL 350 mm x1		

3 Ø 3.5x16mm x7	11 M4x20mm x2	86 128mm x1
-----------------------	---------------------	-------------------

A=B

