

27980255/06


DALTON






BDSK Handels GmbH & Co. KG


















Mergentheimer Straße 59


DE-97084 Würzburg

E-Mail: info@xxxlutz.at







 x80	 x80	 x24	 x8	 x84	 x24	 x16	 x4	 x20
A M6x35mm	B Ø15mm	C 8x30mm	D M7x50mm	E 3.5x14mm	F 4x35mm	G Ø20	H M6x25mm	I
 x16	 x8	 x8	 x4	 x2	 x2	 x2	 x1	
J	K	L	M	N	O	P 4.5x60mm	Q	







1.








2.





3.






4.





5.





6.





7.






	
E	K
3.5x14mm	
x16	x8

8.






	
B	
Ø15mm	
	x12





9.





10.






11.







12.






13.






14.





15.





x2





16.




17.




18.




4.





3.








2.



1.



19.



20.

