























JULY



Article number	PSC	Package
1	x2	1/5
2	x2	2/5
3	x2	3/5
4	x2	4/5
5	x1	4/5
6	x1	5/5




60min

				
Ax6	Bx4	Cx2	Dx2	Ex16
				
Fx16	Gx8	Hx32	Ix4	Jx1
				
Kx1	Lx7	Mx4	Nx1	Ox4
				
Px1	Rx8	Sx8	Tx4	Ux8
				
Vx20	Qx1	 2/5 4/5		




Bx2




Hx8

M8x20




Kx1

1




x2

(H) 50%




Bx2




Hx8

M8x20



Kx1


2




x2

(H) 100%

3



4



4.2x32
Fx16




lx4

Qx1

5




$XX = YY \equiv 90^\circ$






Lx1




Nx1

6




Ex2




Qx1

7




x2

4x20
Vx20





Qx1

8





V 20X






9






Cx1



Dx1




M8x20
Hx8



Kx1


10

1. (H) 50%



M8x60
Rx8

11




M8x16
Gx4

Mx2

Jx1

12/16

12




M8x16
Gx4


Mx2

Jx1

13




14



Ux4




Jx1




Kx1

15

1. (U) 100%
2. (H) 100%






Ux4




Jx1




Kx1


17

1. (U) 100%
2. (H) 100%






18



19



20

