








BUBBLE



ACCESSORY LIST

P07  B.A.M 1x	A28  3,5x50 1x	A16  DbØ8 1x
---	--	--

1 step



2^{step}

