


### Nr 1

002625		x6
000070		x4
000071		x2
000073		x2
000011		x6
004620		x2
004619		x10
000656		x4
000181		x6



--	--	--	--	--	--	--	--	--







This block contains 18 icons arranged in a grid, providing detailed instructions and warnings:

- Top row: 1. A baby and a hand with a diagonal line through them, indicating no baby in the room. 2. A sequence of icons showing the assembly process with a question mark, telephone, and happy face. 3. Two coffee cups: one with steam and a checkmark, the other with a diagonal line through it, indicating no hot drinks.
- Second row: 1. Two floor mat diagrams: one with a checkmark and one with an 'X'. 2. Two cabinet diagrams: one with a checkmark and one with an 'X'. 3. Two window diagrams: one with a diagonal line through it and one without.
- Third row: 1. A hand being washed with water droplets and a '100% COTTON' label. 2. A bottle with a diagonal line through it. 3. A person touching a cabinet with a diagonal line through it. 4. Two people standing on a cabinet with an upward arrow. 5. A person standing on a cabinet with a diagonal line through it.
- Bottom row: 1. A brick wall with a nail being driven into it. 2. A cabinet corner with a diagonal line through it. 3. A person sitting on a cabinet with a diagonal line through it. 4. A fully assembled cabinet.


This block contains several icons and diagrams:

- Top left: A warning triangle with a falling object and a person.
- Top middle: A diagram of a cabinet with a thumbs up and labels 'n26.1' and 'p38'.
- Top right: A diagram of a box with sections 'A' and 'B' and a thumbs up, labeled 'A=B'. Next to it is a diagram of a spray bottle.
- Bottom left: A diagram of a hand holding a pencil, with a crossed-out diagram of a cabinet next to it.
- Bottom right: A calendar for the month of May (MoTu We Th Fr Sa Su) with dates 1-31. Below it is a diagram of a cabinet with a thumbs up and a checkmark, and two circular icons with plus signs.


## 1

- 004620  x2
- 004619  x10
- 000656  x4
- 000181  x6



## 1





## 2



## 2

- 002625  x6
- 000011  x6



## 3

- 000070  $\times$  3,5x13 x4
- 000071  $\phi$  8x40 4x45 x2
- 000073 L-Bracket x2

