














 A 22	 B 39	 B2 10	 C 3	 C5 6	 D2 9
 E1 12	 F2 4	 L=450mm 3	 I1 24	 M2 1	 O 8
 P5 8	 P8 8	 S 3	 T15 4	 U 6	















1

$\varnothing 12/10\text{mm}$  C5	$\varnothing 8 \times 30\text{mm}$  A	$6,4 \times 50\text{mm}$  B	$\varnothing 15/12\text{mm}$  C
2	4	9	3










2

+6x42mm	L=20mm
	
B2	D2
2	3
















3

12/10mm	8x30mm	6,4 x 50mm
		
C5	A	B
4	8	18













4

+6x42mm	L=20mm
	
B2	D2
8	6




5


$\varnothing 8 \times 30 \text{ mm}$ 	 L L=450mm  R	[CD]  I11	$\varnothing 6.3 \times 13 \text{ mm}$  M2	6.5x48x16  F2
10	3		24	4




x2







6

6,4 x 50mm		
		
B	O	E1
4	1	4








7




6,4 x 50mm		
		
B	O	E1
8	1	8



8

 P8 8	 P5 8	 T15 4
--	--	---




9

L=160mm	M4x22mm
	
S	U
3	6



1.



2.

