









No	Name of Hardware	Fig	Q.ty
1	Botl M6x50		6
2	Washer 6x18x2		4
3	Botl M6x30		2
4	Allen Key		1




Step 1:



Step 2:



Step 3:Step 4: