





19090028-01


KNIVS

XXXLutz KG
Roemerstrasse 39
AT-4600 Wels, Austria




A	x 16	B	x 16	C	x 16	D	x 84	E	x 4
									
Φ15 x 12mm		M6 x 35mm		Φ8 x 40mm		M3.5x 15mm		M6 x 15mm	
F	x 8	G	x 2	H	x 6	I	x 24	J	x 24
									
M6 x 30mm		M6 x 35mm		350mm		Φ12 x 12mm		M6 x 24mm	
K	x 4	L	x 18	M	x 1	N	x 12	O	x 2
									
M6 x 45mm									
P	x 4	Q	x 5	R	x 1	S	x 2	T	x 2
									
U	x 8	V	x 2	W	x 2	X	x 2	Y	x 2
									
								M4x37mm	
Z	x 40								
									







1 1600x400x18mm	2 1600x400x18mm	3A 514x398x18mm	3B 514x398x18mm	4A 514x379x18mm
4B 514x379x18mm	5 516x506x18mm	6 510x354x15mm	7 500x354x15mm	8 516x166x18mm
9A 332x100x18mm	9B 332x100x18mm	10 491x100x18mm	11 465x342x5mm	12 524x522x5mm
13 524x512x5mm				





1




E	x 4	F	x 8	G	x 2	K	x 4	L	x 18
									
M6 x 15mm		M6 x 30mm		M6 x 35mm		M6 x 45mm			
M	x 1	P	x 4	R	x 1	S	x 2	T	x 2
									

2




B	x 16	C	x 8
			
M6 x 35mm		Φ8x 40mm	

3




3

$$H = H1 + H2$$




H	x 6
	
350mm	

4




D	x18
	
M3.5 x 15mm	

H2	x 6
	
350mm	




5




A	x 8
	
Φ15 x 12mm	


6



C	x 8
	
Φ8 x 40mm	




7




A	x 8
	
Φ15 x 12mm	

U	x 8
	

8




Z	x 16
	




9


7 7





10




D	x 12
	
M3.5X15MM	




O	x 2
	

V	x 2
	

Q	x 2
	




11



Make sure that the upper and lower positions of step 1 are properly adjusted before proceeding to step 2


D	x 16
	
M3.5X15MM	

12




D	x 12
	
M3.5x 15mm	

N	x 12
	




13




W	x 2
	

14




X	x 2
	



Y	x 2
	
M4x37mm	




15




16



D	x 2
	
M3.5 x 15mm	



17




D	x 6
	
M3.5X15MM	


J	x 24
	
M6X24MM	

Q	x 3
	


18



I	x 12
	
Φ12x 12mm	




19






x3


20



x3



21



D	x 18	H1	x 6
			
M3.5x 15mm		350mm	

22

