







“3994”

versionsnummer: 19.05.2022


Naturholz kann sich werkstoffbedingt verziehen. Durch das Montieren ziehen sich Teile wieder plan.




B5




B1




B2













B3



B4













2

6x  $\phi 8 \times 32$ mm f1






14x  $\phi 15$ #12.5 r1



3






8x  a2

16x  $\phi 3.5 \times 16$ mm p1






3

4





4

5



5

6



5x
k19




16x
I2

4x
φ4x30 mm
p42

10x
3,5x20
p4

10x
φ3.5x35 mm
p80









10x
I9



6

7

26x  s2	4x  φ5x17 mm d3	12x  φ5x17 mm d1	1x  t17	1x  n14	2x  φ3.5x16 mm p1
--	---	--	---	---	--



7