
















25100029-01


XXXLutz KG
Roemerstrasse 39
AT-4600 Wels
















A x22  L35	B x22  m15x12	C x18  m6x30	D x6  m6x55	E x1  m4	H x4  m3x16	H4 x24  m3x15
H5 x38  m4x20	H3 x2  m3x18	N x2 	P x2  m4x38	Q x2  m6x40	R1 x2 	Z x2 
Z1 x4 	X x1  L1225					








A x32	B x32	C x15	W1 x5	E x1	H1 x12	H2 x20
 L35	 m15x12	 m6x30	 m6x30	 m4	 m3x25	 m3x12
H3 x2	H4 x24	H5 x22	N x2	P x2	Q x2	R x8
 m3x18	 m3x15	 m4x20	 m4x38	 m4x38	 m6x40	 M6x19
S x6	T x6	U x12	V x1	Z x2	Z1 x4	
 L300	 L300	 m5x10	 m4x38	 m4x38	 m4x38	






1

H4 x12	Z x2	Z1 x4
 m3x15		




2

A x12	H x4
 L35	 m3x16
R1 x2	
	



3




A x6
L35


C x4
m6x30

H3 x2
m3x18

N x2




4





A x4
L35

C x14
m6x30





5

B x3





6

B x4



7

B x6
m15x12





8


B x6



m15x12







I


II


III


9

B	x3	D	x4	E	x1
					
m15x12		m6x55		m4	






10

H5 x38




11



X	x1	H4	x12
			
L1225		m3x15	




12




A x12




13




B x12



14



15





H1 x12




m3x25



16





H2 x18	T x6
 m3x12	 L300






17







H4 x12	Z x2	Z1 x4
 m3x15		





18






19



20



C x7  m6x30	R x4  M6x19	S x4  L300
---	---	--

U x8  m5x10
--





21

B x1  m15x12





22

B x3











23






B x5



24





25





26

H5 x22




27


P	x2	Q	x2
			
m4x38		m6x40	



28



29





H4 x12



m3x15

30

D	x2	E	x1
			
m6x55		m4	



31

P	x2	Q	x2
			
m4x38		m6x40	

