







1.

MZ186_01


rauch




Typ 1



Typ 2






Typ 3














MZ186

2.




1147



MZ186

Typ 1



4-12x

M4




4-12x

M4x28




2x



2x








2x




8x

M5x10



Typ 2




8x

4x25




8-12x

M4



8-12x

M4x28




4x

4x27




2x



2x








2x

















8x

M5x10






Typ 3





1


8x (1208) M5x10



2




3




4

4-12x (580) M4

4-12x (582) M4x28



Typ 1





4

8x (240) 4x25


8-12x (580) M4

8-12x (582) M4x28

4x (718) 4x27



Typ 2



4

4x (203)

4x30

8x (240)

4x25

4-8x (580)



M4

4-8x (582)


M4x28

4x (718)

4x27






Typ 3



5



2x 1091




6




Ø6mm





17.




18.









11



12



13



14

