












Assemble instruction


27980110/02






A	x21	B	x37	C	x8	D	x8	E	x55	F	x2	G	x1
													
6x35mm		Ø15x12mm		8x30mm		6x30mm		3.5x14mm		7x50mm		M4	
H	x2	I	x12	J	x4	K	x2	L	x2	M	x2	N	x2
													
M6x12mm		M6x28mm		M6x50mm		M6x18mm		6x30mm		Ø30x15mm		4x60mm	
O	x12	P	x4	Q	x1	R	x10	S	x8	T	x2	U	x6
													
Ø20mm												340mm	
V	x6	W	x18	X	x4	Y	x3	Z	x3				
													
340mm		4x35mm		5x17mm									


Assembly details




1




2








3




B	x4	S	x4
			
Ø15x12mm			

4




A	x4	C	x4	E	x12	U	x6
							
6x35mm		8x30mm		3.5x14mm		340mm	

5




B	x4	C	x4	D	x4
					
Ø15x12mm		8x30mm		6x30mm	

6






D	x4
	
6x30mm	

7



8





B	x6
	
Ø15x12mm	

This diagram shows an exploded view of a mechanical assembly. It includes two identical trapezoidal brackets, each labeled with a circled 11. A long rectangular bar, labeled with a circled 12, is positioned between them. A small square plate, labeled P, is shown above each bracket. A screw, labeled J, is shown passing through one of the brackets. A curved metal piece, labeled G, is shown at the bottom right, with a curved arrow indicating its movement.


x 2

G	x1
	
M4	

J	x4
	
M6x50mm	


P	x4
	
	

11




G	x1	H	x2	I	x12	Q	x1
							
M4		M6x12mm		M6x28mm			


12




E	x10	R	x10
			
3.5x14mm			

13




L	x2	M	x2	N	x2
					
6x30mm		Ø30x15mm		4x60mm	

14




X	x4
	
5x17mm	

15






K	x2	G	x1
			
M6x18mm		M4	

16



E	x4	T	x2
			
3.5x14mm			


17



E	x8
3.5x14mm	

18


x 3



A	x15	E	x3	Z	x3
6x35mm		3.5x14mm			

19


x 3



W	x18
	
4x35mm	




20

x 3



B	x15	O	x12
			
Ø15x12mm		Ø20mm	

21



x 3

E	x12	V	x6
3.5x14mm		340mm	

22

