






LINE 5L - KOMMODE







Ø5
Ø8








1200 mm


400 mm

480 mm






LINE 5L - KOMMODE


A0 8 x 30mm  x46	B1 f 7 x 50 mm  x10	C0  x18
B2 f 7 x 70 mm  x4	C2  x32	C7 16mm  x32
D0 3 x 15 mm  x32	D21 5 x 13 mm  x41	D5 3,5 x 16 mm  x30
D14 4 x 35 mm  x12	K 4mm  x1	M1  x32
N2 L-400  x5	T2  x4	U0  x10
E0 5 x 50 mm 8 x 50 mm  x1	P0  x1	



LINE 5L - KOMMODE




1	1131	475	16	1	1/2
2	1131	475	16	1	1/2
3	400	480	22	1	2/2
4	400	480	22	1	2/2
5	400	140	16	4	1/2
6	400	140	16	4	1/2
7	309	138	16	4	1/2
8	400	90	16	1	1/2
9	400	90	16	1	1/2
10	309	88	16	1	1/2
11	360	209	16	4	1/2
12	360	142	16	1	1/2
13	366	59	32	5	1/2
14	319	394	3	5	1/2
15	1141	376	3	1	1/2
16					2/2







1

A0 8 x 30mm 	x4	C7 16mm 	x2	C2 	x5
D21 5 x 13 mm 	x20	N2 L-400 	x5		






2

A0 8 x 30mm 	x10	C7 16mm 	x10
--	------------	--	------------





3

A0 8 x 30mm 	x4	C7 16mm 	x2	C2 	x5
D21 5 x 13 mm 	x20	N2 L-400 	x5		




4


C2 	x4	D21 5 x 13 mm 	x1	P0 	x1
--	-----------	--	-----------	--	-----------




5▶





x4





x4



6▶




7▶




8▶

A0 8 x 30mm 	x2	C7  16mm	x2
--	-----------	--	-----------




9▶

A0 8 x 30mm 	x2
--	-----------




10▶




C2 	x2	U0 	x2
--	-----------	--	-----------





11▶





12▶



13▶









14▶






15▶

(D0) 3 x 15 mm 	x8	(M1) 	x8
---	-----------	--	-----------






16▶



(B1) f 7 x 50 mm 	x8	(K) 4mm 	x1
---	-----------	--	-----------




17▶




18▶



19▶




x4








20▶









D0	3 x 15 mm	x20	M1		x20
					





x5



16▶



17▶



18▶

