




+






+





R

BOX 1/2


2x





2x



1x a




1x b




11x c

M8 x 60 mm




11x d

Ø 8 / Ø 24 mm




11x e

M8




4x f

6,3 x 16 mm



8x g


19 cm




1x h

13 mm


BOX 2/2




6




1




7




8





9





10








1.



2.




3.




4.

3x (d)



Ø 8 / Ø 24 mm

3x (e)




M8

1x (h)




13 mm



5.



1x (b)



2x (f)




6,3 x 16 mm




6.


3x (c)



M8 x 60 mm



7.



8.






Ø 8 / Ø 24 mm




M8




13 mm




9.





10.





11.




12.







13.





14.




15.






16.




17.





18.


2x (d)  Ø 8 / Ø 24 mm	2qx (e)  M8	1x (h)  13 mm
--	--	--




19.




20.



21.



22.



23.

