







Polina



1


2

3



ZC7338

1	1x
2	4x
3	1x



1/1

A

M6X13



4x

B

M6X20



4x

C


Ø18xØ6x1.5



8x

D


5MM



1x


I.

1



- A M6x13 4x
- C Ø18xØ6x1.5 4x
- D 5MM 1x
- 100%



2




- B M6x20 4x
- C Ø18xØ6x1.5 4x
- D 5MM 1x
- 80%

II.

3

D		5MM
		1x
		



LE TRI + FACILE  

Séparez les éléments avant de trier