


Spiegelschrank



1



2









3

















- DE** Montageanleitung
- GB** Assembly instruction
- FR** Notice de montage
- ES** Insstrucciones de montaje
- IT** Istruzioni di montaggio
- PT** Instruções de montagem
- NL** Montage-instructies
- DK** Monteringsvejledning
- SE** Monteringsanvisningar
- FI** Aasennusohjeet
- IS** Leiðbeiningar um samsetningu
- EE** Paigaldusjuhendid
- LT** Surinkimo instrukcijos
- LV** Montažas instrukciju
- TR** Montaj talimatları

- PL** Instrukcja montażu
- CZ** Montážní návod
- SK** Montážny návod
- HR** Upute za montažu
- MT** Istruzzjonijiet
- SI** Navodila za montažo
- HU** Szerelési útmutató
- RO** Instrucțiuni de montaj
- BG** инструкции за монтаж
- CN** 彙編指令
- GR** οδηγίες συναρμολόγησης
- ME** Uputstvo za montažu
- MK** собранието инструкции
- RU** инструкции по сборке
- RS** uputstva za montazu










230 V AC, 50 Hz




5 W



120.000 x



ca. 0 s



30.000 h






4.000 K



350 Lumen



$\leq 120^\circ$







230 V AC, 50 Hz




max. 16 A





1.
1.1




1.2



2.
2.1





2.2





3.





3.1








3.2




4.




5.




5.1




5.2




5.3




5.4




6.






7.






8.




9.




10.







11.



12.



13.




14.

1137




1147
4x




7x60 mm

1137
1x






SW4

1147






15.




16.






16.1



16.2





17.






DIN VDE 0100-701







18.




19.






19.1




19.2











19.3





20.



21.





22.



Montage - montage - assembly

Justierung - ajustment - adjustment



Demontage - démanèment
- dismantling

