









LINA

05860006 / 02

05860006 / 03



festziehen / tighten / Затягивать /
serrer / stringere / utáhnout / vasttrekken /
zategnuti / strângere / zwiázac / zacisn'æ
szorosan meghúzni / pevne dotiahnuť /
trdno pritegniti / затянуть / dra et



eindrücken / press in / enfoncer / wcisnąć
ribattere / zatlačit / Вкарайте / indrukken
benyomni / stlačit' / vtisniti / tryck in
introducere prin apăsare / вдавить



ausmessen / measure / mesurer /
misurare / opmeten / izmeriti / mîara /
kimérni / izmeriti / măsurare / измерить
změřit / Измерете / mät upp / zmierzyc



drücken / press / presser / stisknout /
Натиснете vtisniti / nasinac / drukken /
pritisnuti / nacinac / pritisniti / нажать /
(meg)nyomni / apăsare / tryck fast / nacinac




einschlagen / hammer in / beverni / sla in
frapper au marteau / infossare / Zabit' /
zarazit / Набийте / zabiti / wbić
introducere prin bătaie / забить / zatlouct










Drehen - wenden / przekreć / odwrócić /
Keren - omdraaien / Girare - Ruotare /
Okrenuti - ubrnuti / Retourner - renverser /
Turn over - turn around / Otočite - obratite /
Завъртете - обърнете / Obrnite list /
Întoarceți - roțiți / Vrid runt - vänd /
прокрутить - повернуть / otočit - obrátit
elforgatni - megfordítani






L H B
750x682x402mm










			 pos.	 box
1	a1	666mm x 400mm x 16mm	1	6/7
2	a2	666mm x 400mm x 16mm	1	6/7
3	b1	750mm x 402mm x 16mm	1	6/7
4	c1	714mm x 60mm x 16 mm	2	6/7
5	d1	198mm x 710mm x 16mm	3	6/7
6	e1	350mm x 80mm x 16mm	3	6/7
7	e2	350mm x 80mm x 16mm	3	6/7
8	f1	656mm x 80mm x 16mm	3	6/7
9	g1	633mm x 364mm x 3.2mm	2	6/7
10	h1	355mm x 686mm x 3.2m	3	6/7








1  Ø15x12mm x14	2  Ø6x45/34mm x14	3  Ø3.5x16mm x70	4  Ø8x35mm x14	5  Ø7x50mm x6
86  x1	11  M4x20mm x3	25  6x16x53mm x6	46  Ø15mm x6	69  9x20x100mm x9
24/RL  350 mm x3	24/DL  350 mm x3	24/CR  350 mm x3	24/CL  350 mm x3	16  Ø8x50mm x1
15  6x70mm x1	43  90x10x30mm x1			










3		4		1		2	
	Ø3.5x16mmx18		8x35mm x4		Ø15x12mm x4		6x45/34mm x4
24C/R		24C/L					
	350 mm x3		350 mm x3				













3		25	
	ø 3.5x16mm x24		x6
69			
	x9		





 **A=B**



x3

1		2		4		5		46	
	Ø 15x12mm X6		6x45/34mm X6		Ø 8x35mm X6		Ø 7x50mm X6		Ø 15mm X6









3 Ø 3.5x16mm x21	11 M4x20mm x3	24\DL 350 mm x3	24\RL 350 mm x3	86 128mm x3
------------------------	---------------------	-----------------------	-----------------------	-------------------


x3




A=B



V





15 Ø 6x70mm x1	43 90x10x32mm x1
3 Ø3.5x16mm x2	16 Ø8x50 x4

