








U 100 ZAP





 A 20 L=450mm	 B 10 +5/19mm	 B2 4 L1=680mm	 E1 8 +5.0x13mm	 E9 2 12 +4.0x30mm	 F2 4 0,05 1	 HG 4 +4.0x45mm 2
 I5 2	 J 4	 L1 1	 M 12	 O 1	 O11 1	 P4 2
 P5 20	 P7 15-20	 P24 4	 R2 8	 S30 4		




ISM-KUH-01042

1




x2

2














3




4

6.5x48x16 F2	∅8x30mm A	∅35/0mm HG	∅3.5x13mm P5	L=450mm I5	∅5.0x13mm M
4	8	4	8	1	6




5

6,4 x 50mm



B

4





O

1




E1

4




E1




6

6,4 x 50mm



B

4




O

1




E1

4





E1




7

L=450mm  I5 1	±5.0x13mm  M 6	6,4 x 50mm  B 2	 O 1
--	---	--	--





KUH.90025



8

L1=680mm  L1 1
--



KUH.60022

KUH.60022



9

+3.0x20mm



P7

15-20



P7



7mm

P7

10

+4.0x45mm




P4

2




E9

2



P4

P4



KUH.90021


11

±5/19mm




J

4



KUH.30013




12

±4.0x35mm



P24

4




KUH.20006

P24

13

L=450mm



I5


1

±3.5x13mm





P5








12





x2



+4.0x30mm	
	
R2	S30
8	4



KUH.70021



KUH.70021

