















GO 5







05860114/03






1	a1/a2	760mm x 330mm x 16mm	2	1/2
2	b1/b2	760mm x 330mm x 16mm	2	1/2
3	c1/c2	1200mm x 350mm x 16mm	2	1/2
4	d1	375mm x 330mm x 16mm	2	1/2
5	e1,e2	300mm x 100mm x 16mm	8	1/2
6	f1	325mm x 100mm x 16mm	4	1/2
8	g1	775mm x 396mm x 16mm	2	2/2
9	h1	396mm x 170mm x 16mm	4	2/2
10	h2	396mm x 203mm x 16mm	8	2/2
11	k1	353mm x 305mm x 4mm	4	2/2
12	j1	398mm x 788mm x 4mm	3	2/2



2  $\varnothing 6 \times 45/34 \text{ mm}$ x16	1  $\varnothing 15 \times 12 \text{ mm}$ x16	4  $8 \times 35 \text{ mm}$ x24	3  $3.5 \times 16 \text{ mm}$ x90	25  30 mm x5
24\CR  300 mm x4	24\CL  300 mm x4	24\RL  300 mm x4	24\DL  300 mm x4	149  $3.5 \times 25 \text{ mm}$ x23
15  $\varnothing 6 \times 70 \text{ mm}$ x1	16  $\varnothing 8 \times 50 \text{ mm}$ x1	43  $90 \times 10 \times 30 \text{ mm}$ x1	5  $\varnothing 7 \times 50 \text{ mm}$ x16	 4 mm x1
86  128 mm x6	11  $M4 \times 20 \text{ mm}$ x12	9  $90 \times 10 \times 30 \text{ mm}$ x4	10  $\varnothing 6.3 \times 11 \text{ mm}$ x8	73  $15 \times 15 \times 7 \text{ mm}$ x8
58  128 mm x8				





A=B

