




# SPARKS 30J6\_\_50




























| NO | Dim.[mm] |     |    | Col.-No | Qty |
|----|----------|-----|----|---------|-----|
| 1  | 800      | 700 | 20 | 1/1     | 1   |





15 min







1




D20

x6



2



KR3

x3

