








SMART




 A	 B	 B2	 C	 D2	 E	 E1	 F2
36 15x5mm  F4	12 20/8mm  J14	2 35/0mm  HG	10 L=400mm  I5	12 5/16mm  J3	10  L	10 75x30x15mm  L19	8 6.3x13mm  M2
1 5.0x20mm  M5	3  O	6 12/10mm  C5	1 3.5x13mm  P5	8 3.0x20mm  P7	2 4.0x30mm  R2	1 L=128mm  S	3  M1
3	1	2	20	12	8	4	2






ISM-KUH-01608







SMART



Colli
1/3




KUH.10246	1045x550x16mm	x1
KUH.10298	1045x550x16mm	x1




KUH.10299	815x550x16mm	x1
KUH.10300	815x550x16mm	x1
KUH.50014	668x486x16mm	x1
KUH.60264	683x500x2,5mm	x1
KUH.70931	496x128x16mm	x1
KUH.70695	677x496x16mm	x1
KUH.70696	545x496x16mm	x1

16x30mm	6,4 x 50mm	16x42mm	16x12mm	L=20mm
36	12	2	10	12
		6,5x48x16	15x5mm	120/8mm
10	10	8	1	3
135/0mm	L=400mm	15/16mm	75x30x15mm	
6	1	8	2	1
16,3x13mm	15,0x20mm	12/10mm	13,5x13mm	
3	3	1	2	20
13,0x20mm	14,0x30mm	L=128mm		
12	8	4	2	

Colli
2/3




KUH.20083	601x568x16mm	x1
KUH.40008	567x485x16mm	x1
KUH.70582	908x596x16mm	x1
KUH.90010	567x100x16mm	x1
KUH.90116	567x130x16mm	x1



KUH.20113	1001x600x38mm	x1
KUH.30062	475x430x16mm	x1
KUH.40140	475x485x16mm	x1
KUH.40141	967x486x16mm	x1
KUH.60244	398x428x2,5mm	x1
KUH.90213	967x130x16mm	x1
WST.0211	400x80x12mm	x1
WST.0212	400x80x12mm	x1
WST.0081	418x80x12mm	x1

Colli
3/3













KUH.10242	580x290x16mm	x2
KUH.40120	995x276x16mm	x2
KUH.40122	995x276x16mm	x1
KUH.60175	1013x287x2,5mm	x1
KUH.60176	1013x287x2,5mm	x1
KUH.70588	1024x294x16mm	x1

16x30mm	6,4 x 50mm		135/0mm	
12	12	12	2	2
	13,0x25mm			13,5x13mm
2	1	3	1	6
13,0x20mm	14,0x30mm	14,0x30mm	L=128mm	
15-20	4	2	1	




1

$\varnothing 8 \times 30 \text{mm}$  A 10	$\varnothing 15/12 \text{mm}$  C 4	$L=20 \text{mm}$  D2 4	$6.5 \times 48 \times 16$  F2 4
--	---	---	--







2

$\varnothing 35/0 \text{mm}$  HG 2	$\varnothing 3.5 \times 13 \text{mm}$  P5 4
--	---






3




$6,4 \times 50 \text{mm}$  B 3	 O 1
---	---






4










5









6







7



±4.0x30mm	L=128mm
R2	S
2	1








8











±8x30mm A 4	±12/10mm C5 2
----------------------------------	------------------------------------


9




10



11

















L=400mm L5 1	±3.5x13mm P5 6
-----------------------------------	-------------------------------------






12

$\varnothing 8 \times 30 \text{mm}$  A	$\varnothing 15/12 \text{mm}$  C	L=20mm  D2	6.5x48x16  F2
18  I5	6  J14	6  M2	4  M5
1	3	3	1







13





$\varnothing 35/0 \text{mm}$  HG	$\varnothing 3.5 \times 13 \text{mm}$  P5
4	8






14








15






16





17





18




19






$\varnothing 15 \times 5 \text{ mm}$ F4 1	 L 2	$\varnothing 3.0 \times 20 \text{ mm}$ P7 12
--	-------------------	---





20




$\varnothing 5/16 \text{ mm}$ J3 8








21



22















4.0x30mm	L=128mm
R2	S
6	3



23




$\varnothing 8 \times 30 \text{mm}$  A	$\varnothing 15/12 \text{mm}$  C	$L=20 \text{mm}$  D2	$6.5 \times 48 \times 16$  F2
18  I5	6  J14	6  M2	4  M7
1	3	3	3

6.5x48x16
F2








24






$\varnothing 35/0 \text{mm}$  HG	$\varnothing 3.5 \times 13 \text{mm}$  P5
4	8






25








26








27







28




29






$\varnothing 15 \times 5 \text{ mm}$ F4 1	 L 2	$\varnothing 3.0 \times 20 \text{ mm}$ P7 12
--	-------------------	---










30




$\varnothing 5/16 \text{ mm}$ J3 8








31


















32



$\pm 4.0 \times 30 \text{ mm}$ R2 6	$L=128 \text{ mm}$ S 3
---	--









4x3.5x13mm	75x30x15mm
P5	L19
2	1


1.




2.



3.



4.



5.

