
















H3GT12






NO.	SIZE	QTY
1	1764*377*16	1
2	1800*396*16	1
3	395*354*16	2
4	298*349*16	2
5	584*348*16	1
6	1764*94*16	1
7	1774*269*5	1
8	292*590*18	2

		
A	M6*40	22pcs
B	Ø15*13.5	22pcs
C	Ø8*30	22pcs
		
I	M6*12mm	24pcs
J	M7*50mm	4pcs
L	H=170	4pcs
		
M	/	4set
D	M3*12	32pcs
Z	Ø20	22pcs
		
T	H=169	2pcs




STEP 1:

		
I	M6*12mm	24pcs
L	H=170	4pcs
T	H=169	2pcs




STEP 2:





		
A	M6*40	4pcs
B	Ø15*13.5	4pcs
C	Ø8*30	4pcs

STEP 3:


		
A	M6*40	6pcs
B	Ø15*13.5	6pcs
C	Ø8*30	6pcs



STEP 4:

		
A	M6*40	12pcs
B	Ø15*13.5	12pcs
C	Ø8*30	12pcs








STEP 5:

		
J	M7*50mm	4pcs





STEP 6:



			
M	/ 4set	D	M3*12 32pcs



BOTTOM





STEP 7:



move the door into orbit round rail.

STEP 8:



Warning hands pinching

