









SPOT














1	A41	768x304x16mm	2	4/7
2	B41	700x304x16mm	2	4/7
4	C41	711x397x16mm	2	4/7
5	D41	768x294x16mm	2	4/7
6	E41	696x398x3.7mm	2	4/7

3	$\varnothing 3.5 \times 16 \text{mm}$ x34	4	$\varnothing 8 \times 35 \text{mm}$ x8	5	$\varnothing 7 \times 50 \text{mm}$ x8	7	x4	10	$\varnothing 6.3 \times 11 \text{mm}$ x8
73	$\varnothing 15 \times 15 \times 7 \text{mm}$ x4	15	$\varnothing 6 \times 70 \text{mm}$ x2	16	$\varnothing 8 \times 50 \text{mm}$ x2	17	x2	17	$\varnothing 8$ x4

0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190







A=B

