






The diagram illustrates a mechanical assembly with the following components and connections:

- 1**: A long horizontal bar at the top.
- 2**: Two vertical bars, one on each side, connected to the ends of bar 1.
- 3**: Two angled support bars, one on each side, connecting the lower part of bar 2 to bar 4.
- 4**: A horizontal bar at the bottom, supported by the angled bars 3.
- A**: A small component at the top end of each vertical bar 2.
- B**: A small component on the side of each vertical bar 2, near the bottom.
- C**: A small component on the side of each vertical bar 2, below B.
- D**: Two circular components at the bottom, one on each side, connected to the angled bars 3.
- E**: A label pointing to the base of the assembly, which includes the circular components D.

1		1
2		2
3		2
4		2

A		2
B		2
C		2
D		2
E		4