











ASSEMBLY INSTRUCTION

AUFBAUANLEITUNG / Návod / Instruktioner

	MODEL 5230	
	29100013	
	 20 MIN	 X 2

			 A X4 M6 X 20MM
			 B X8 M8 X 35MM
			 C X2 M8 X 100MM
			 D X4 M6
			 E X4
1		X 1	 F X2
2		X 2	 G X2
3		X 1	 H X1 M4
			 I X1 M5
			 J X2