






GOTLAND
HOERNUM
TRONDHEIM
3100-8301
8101-3300
2019-04/1

D	MONTAGEANLEITUNG BEDIENUNGSANLEITUNG	GB	ASSEMBLY INSTRUCTIONS INSTRUCTION MANUAL
NL	HANDLEIDING VOOR DE MONTAGE GEBRUIKSAANWIJZING	PL	INSTRUKCJA MONTAŻU INSTRUKCJA OBSŁUGI
TR	MONTAJ TALIMATI KULLANIM KLAVUZU	RU	ИНСТРУКЦИЯ ПО МОНТАЖУ ИНСТРУКЦИЯ ПО ЭКСПЛУАТАЦИИ
RO	INSTRUCȚIUNI DE INSTALARE INSTRUCȚIUNI DE UTILIZARE	IT	ISTRUZIONI DI MONTAGGIO MANUALE DI ISTRUZIONI
FR	NOTICE DE MONTAGE MANUEL INSTRUCTIONS	SK	MONTÁŽNY NÁVOD NÁVOD NA POUŽITIE
HU	KÖZGYŰLÉS UTASÍTÁSOK KEZELÉSI UTASÍTÁS	CZ	MONTÁŽNÍ NÁVOD NÁVOD K POUŽITÍ
SI	NAVODILA ZA MONTAŽO NAVODILA ZA UPORABO	PT	INSTRUÇÕES DE MONTAGEM MANUAL DO USUÁRIO
ES	INSTRUCCIONES DE MONTAJE MANUAL DEL USUARIO	HR	UPUTE ZA MONTAŽU UPUTE ZA UPOTREBU







Service · Dienstverlening · Servis · Servis · Сервисная служба · Serviciu · Services · Servizio
·Servisný list · Szolgáltatás · Servisní list

Name · Naam · Nazwa · Ísim · Название · Nume · Nome · Název · Názov ·
Název · Neve








GOTLAND;HOERNUM; TRONDHEIM

Typ · Type · Tip · Тип · Tipo · Típus







☎ 3100-8301; 8101-3300









v1










v2








v3








v4











v1 v2



v3




v4




A large diagram showing a cylindrical component with a threaded rod. The height of the cylinder is labeled as 100/120mm. A curved arrow indicates the direction of assembly. A large exclamation mark is shown. A diagram shows a hand holding a component. A diagram shows a component being inserted into a base, marked with a checkmark. A diagram shows a component being inserted into a base, marked with an X.

1



2



3

