












13520017/03





XXXLutz KG
Roemerstrasse 39
AT-4600 Wels
Austria





1	800*400*18	1x
2	800*400*18	1x
3	804*399*36	1x
4	804*399*36	1x
5	804*100*16	1x
6A/B	814*323*5	2x
7	722*198.5*18	2x

8	722*198.5*18	2x
9	682*120*12	4x
10	350*120*12	4x
11	350*120*12	4x
12	337*100*12	4x
13	692*348*5	4x
14	726*60*16	2x




A=10




M6*40mm

B=12



$\Phi 8*30\text{mm}$

C=10




$\Phi 15*12\text{mm}$

D=50




$\Phi 21\text{mm}$


E=12



F2=1



G=12




M6*16mm

H=1




M4

J1=4




H210mm

J2=1



H207mm

N=4



O=40




M6*34mm

P=40




$\Phi 12*10.5\text{mm}$

Q=6



$\Phi 7*50\text{mm}$

V1=48



M3.5*12mm

Z1=12





$\Phi 10*2.5\text{mm}$



Z2=12




$\Phi 13*1\text{mm}$










3





4





5




6








8




9



10-1



10-2



10-3

