



LOUISE
42010159-01


XXXLUTZ KG
Roemerstrasse 39
AT-4600 Wels, Austria



1




15




A		M6x40	4
B		M6x12	10
C		Ø16	7
D		M4	1
E			4
F			2


1




A		M6x40	4
D		M4	1




2




B		M6x12	8
D		M4	1
E			4




3







C		Ø16	7
---	--	-----	---



4



Vorsicht Glas!




F			2
---	--	--	---




LOUISE
42010159-01


BDSK Handels GmbH & Co. KG
Mergenthaler Straße 59
DE-97084 Würzburg
Germany



1




15




A	M6x40	4
B	M6x12	10
C	$\phi 16$	7
D	M4	1
E		4
F		2


1




A	M6x40	4
D	M4	1




2




B	M6x12	8
D	M4	1
E		4




3







C	$\phi 16$	7
---	-----------	---



4



Vorsicht Glas!



F		2
---	--	---

