














SERVICEKARTE/SERVICECARD



Modellname/Modelname: BE-0823			Ausführung: Fichte massiv geölt Finishing: Spruce massive oiled		
Modellnummer: 1014701		Modellnummer: 1014705		Modellnummer: 1014713	
140x200		140x200		140x200	
Modellnummer: 1014702		Modellnummer: 1014706		Modellnummer: 1014714	
160x200		160x200		160x200	
Modellnummer: 1014703		Modellnummer: 1014707		Modellnummer: 1014715	
180x200		180x200		180x200	
Modellnummer: 1014704		Modellnummer: 1014708		Modellnummer: 1014716	
200x200		200x200		200x200	

71306










DE: Sehr geehrter Kunde, Sehr geehrte Kundin!
 Fehlt Ihnen ein Beschlagteil oder ist es Defekt? Kein Problem! Nutzen Sie unsere Servicekarte!
 Unser Direkt-Bestellservice für fehlende/defekte Beschlagteile:
 Kontaktieren Sie uns telefonisch unter Tel. +499503/5033-114 oder senden Sie uns eine E-Mail an kundendienst@3s-frankenmoebel.de.
 Bitte geben Sie dabei folgende Pflicht-Informationen an: -> Auftragsnummer, Artikelnummer, Nummer des Beschlagteils,
 fehlende/defekte Menge, und den Grund der Beanstandung, ob es sich um ein defektes oder fehlendes Beschlagteil handelt. Tragen Sie
 die benötigte Menge ein. Mailen Sie uns die vollständig ausgefüllte Servicekarte zu, um die Bearbeitung zu ermöglichen. Für andere
 Beanstandungen / Beschädigungen an Ihrem Möbelstück wenden Sie sich bitte direkt an Ihr Möbelhaus.

EN: Dear customer!
 Are you missing a fitting part or is it defective? No problem! Use our service card!
 Our direct ordering service for missing/defective fitting parts:
 Contact us by telephone on +499503/5033-114 or send us an e-mail to kundendienst@3s-frankenmoebel.de.
 Please include the following mandatory information: -> Order number, article number, number of the fitting part, missing/defective
 quantity, and the reason for the complaint, whether it is a defective or missing fitting part. Enter the required quantity.
 Mail us the completed service card to enable processing.
 For other complaints/damage to your furniture, please contact your furniture store directly.

						M6x20  L x 8	SW 4 	SW 5 	Filz Felt  K x 4
3,5x16  A x 54	 B x 8	Ø10x40  C x 12	8x35  D x 12	M6x50  E x 12	M6x75  F x 4	M6x30  G x 4	 H x 8	 I x 2	 J x 2

Grund der Beanstandung/Reason for appeal.....
 Name/Name:.....Telefon/Phone:.....
 PLZ/Place:.....Ort/Location.....Hause-Nr./Home-Nr.:.....


				
				
				




BETT/BED 0823, 0824, 0825 MONTAGEANLEITUNG/ASSEMBLYINSTRUCTIONS




40 Minutes




7




7a



7b




5a



14

0823


5b



15

0824

5c



9

10

11

0825




M6x20

Lx8




M6x20

Lx6



Ø10x40

Cx6




35x35x90

Mx2



3,5x16

Ax12



Ø10x40

Cx4



8x35

Dx2



M6x50

Ex4



M6x30

Gx4




3,5x16

Ax54



Bx8



Ø10x40

Cx12




8x35

Dx12



M6x50

Ex12




M6x75

Fx4




M6x30

Gx4



SW 4

Hx8



SW 5

Ix2




Filz
Felt

Kx4

Jx2


1+2

1.




3,5x16		Ø10x40	8x35	M6x50	SW 5
					
Ax24	Bx6	Cx8	Dx4	Ex4	

2.




3,5x16		M6x75	SW 4	Filz Felt	Ø10x40
					
Ax4	Bx1	Fx4		Kx2	Cx4

3.




8x35  Dx4	M6x50  Ex4	SW 5 
---	--	--

4.




3,5x16  Ax4	 Bx1	8x35  Dx4	M6x50  Ex4	SW 5 
--	--	--	---	---

5a.




M6x20 L x 8	SW 4 	Filz Felt K x 2	8x35 D x 4	M6x50 E x 4
--------------------	----------	------------------------	-------------------	--------------------

5b.




M6x20 L x 6	Ø10x40 C x 6	SW 4 	3,5x16 A x 12	35x35x90 M x 2
--------------------	---------------------	----------	----------------------	-----------------------

5c.




Ø10x40  Cx 4	8x35  Dx 2	M6x50  Ex 2	SW 5 	Filz Felt  Kx2	M6x30  Gx4
--	--	---	--	--	--


6.




7



7a




7b



M6x30  Gx4	SW 4 
---	---

7.



8.

